




29-008 (Sony Headunits)



This adaptor has been specifically developed for Sony's 2004 + range of headunits.

Older units require the link leads within the plug to be removed.

This can be done by either de-pinning the block using a jewellers screw driver or alternatively cutting the wire, ensuring the ends are well insulated

These link leads need to be removed on older Sony headunits.

*N.B. This adaptor is only compatible with Software Version 25 or above .


In Car Technologies Ltd

2 Leigham Units, Silvertown Rd
Matford Park, Exeter
Devon EX2 8HY . UK

E-Mail: sales@incartec.co.uk
Website: www.incartec.co.uk



29-008 (Sony Headunits)



This adaptor has been specifically developed for Sony's 2004 + range of headunits.

Older units require the link leads within the plug to be removed.

This can be done by either de-pinning the block using a jewellers screw driver or alternatively cutting the wire, ensuring the ends are well insulated

These link leads need to be removed on older Sony headunits.

*N.B. This adaptor is only compatible with Software version 25 or above .


In Car Technologies Ltd

2 Leigham Units, Silvertown Rd
Matford Park, Exeter
Devon EX2 8HY . UK

E-Mail: sales@incartec.co.uk
Website: www.incartec.co.uk



29-008 (Sony Headunits)



This adaptor has been specifically developed for Sony's 2004 + range of headunits.

Older units require the link leads within the plug to be removed.

This can be done by either de-pinning the block using a jewellers screw driver or alternatively cutting the wire, ensuring the ends are well insulated

These link leads need to be removed on older Sony headunits.

*N.B. This adaptor is only compatible with Software version 25 or above


In Car Technologies Ltd

2 Leigham Units, Silvertown Rd
Matford Park, Exeter
Devon EX2 8HY . UK

E-Mail: sales@incartec.co.uk
Website: www.incartec.co.uk



29-008 (Sony Headunits)



This adaptor has been specifically developed for Sony's 2004 + range of headunits.

Older units require the link leads within the plug to be removed.

This can be done by either de-pinning the block using a jewellers screw driver or alternatively cutting the wire, ensuring the ends are well insulated

These link leads need to be removed on older Sony headunits.

N.b. This adaptor is only compatible with software version 25 or above


In Car Technologies Ltd

2 Leigham Units, Silvertown Rd
Matford Park, Exeter
Devon EX2 8HY . UK

E-Mail: sales@incartec.co.uk
Website: www.incartec.co.uk



29-008 (Sony Headunits)



This adaptor has been specifically developed for Sony's 2004 + range of headunits.

Older units require the link leads within the plug to be removed.

This can be done by either de-pinning the block using a jewellers screw driver or alternatively cutting the wire, ensuring the ends are well insulated

These link leads need to be removed on older Sony headunits.

N.b. This adaptor is only compatible with Software version 25 or above .


In Car Technologies Ltd

2 Leigham Units, Silvertown Rd
Matford Park, Exeter
Devon EX2 8HY . UK

E-Mail: sales@incartec.co.uk
Website: www.incartec.co.uk



29-008 (Sony Headunits)



This adaptor has been specifically developed for Sony's 2004 + range of headunits.

Older units require the link leads within the plug to be removed.

This can be done by either de-pinning the block using a jewellers screw driver or alternatively cutting the wire, ensuring the ends are well insulated

These link leads need to be removed on older Sony headunits.

*B.B. This adaptor is only compatible with software version 25 or above .

In Car Technologies Ltd

2 Leigham Units, Silvertown Rd
Matford Park, Exeter
Devon EX2 8HY . UK

E-Mail: sales@incartec.co.uk
Website: www.incartec.co.uk